NBS1R-1216 (R) 77-1216

FE-3800-10 Dist. Category UC-90C

MATERIALS RESEARCH FOR CLEAN UTILIZATION OF COAL

QUARTERLY PROGRESS REPORT
October 1 - December 31, 1976
(JANUARY)

Samuel J. Schneider Project Manager

Institute for Material. Research National Bureau of Standards Washington, D. C. 20234

PREPARED FOR THE UNITED STATES
ENERGY RESEARCH AND DEVELOPMENT ADMINISTRATION

Under Contract No. E(49-1)-3800


"This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the United States ERDA, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the corracy, completeness, or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not warrante privately owned rights."



TABLE OF CONTENTS

				PAGE
I.	OBJ	ECTI	VE AND SCOPE OF WORK	1
II.	SUM	MARY	OF PROGRESS TO DATE	1
III.	DET	AILE	D DESCRIPTION OF TECHNICAL PROGRESS	2
	1.	Met	al Corrosion	2
		a.	Constant Strain-Rate Test	2
		ъ.	Pre-Cracked Fracture Test	18
	2.	Cer	amic Deformation, Fracture and Erosion	22
	3.	Che	mical Degradation	23
		a.	Reactions and Transformations	23
		ъ.	Slag Characterization	24
		c.	Vaporization and Chemical Transport	29
	4.	Fai	Ture Avoidance Programs.	30







I. OBJECTIVE AND SCOPE OF WORK

Coal Gasification processes require the handling and containment of corrosive gases and liquids at high temperature and pressures, and also the handling of flowing coal particles in this environment. These severe environments cause materials failures which inhibit successful and longtime operation of the gasification systems. The project entails investigations on the wear, corrosion, chemical degradation, fracture, and deformation processes which lead to the breakdown of metals and ceramics currently being utilized in pilot plants. Studies will also be carried out on new candidate materials considered for improved performance. Special emphasis will be dovoted to the development of test methods, especially short-time procedures, to evaluate the durability of materials in the gasification environments. These methods will focus on wear, impact erosion, stress corrosion, strength, deformation, slow crack growth and chemical degradation of refractories. A system has been initiated to abstract and compile all significant operating incidents from coal corversion plants. This program will provide a central information center where problems of common interest can be identified and analyzed to avoid unnecessary failures and lead to the selection of improved materials for coal coversion and utilization. Active consultation to ERDA and associated contractors will be provided as requested.

II. SUMMARY OF PROGRESS TO DATE

The summary of progress is contained in the individual task progress and plans - Section III.



III. DETAILED DESCRIPTION OF TECHNICAL PROGRESS

- 1. Metal Corrosion
- a. Constant Strain-Rate Test (G. M. Ugiansky and C. E. Johnson, 312.04)

Progress: The investigation of the cause of embrittlement of type 310 stainless steel at elevated temperatures and at slow strain rates has continued. Comparisons were made between embrittled specimens and non-embrittled specimens of 310 SS and other alloys. Microscopic examination of the cross-sections of 310, 310 S, 347 SS, and Incolov 800 tested at 540°C (1000°F) in H₂S plus steam or H₂S saturated with water vapor at room temperature revealed internal intergranular cracking in 310 SS that was tested at a strain rate of 3.6 \times 10⁻⁶ s⁻¹ as well as surface cracks progressing into the bulk of the specimen (Fig. 1); whereas, a 310 SS specimen tested at the faster strain rate of 1.3 \times 10⁻⁴ s⁻¹ (in the same environment and at the same temperature) shows a ductile type fracture with no internal or surface cracks (Fig. 2). Surface cracking of 310 3S was detected in specimens up to a maximum strain rate of 7.2 \times 10⁻⁶ ; ⁻¹ when tested at 540°C (1000°F) (Fig. 3). The necking which can be seen when Fig. 1 and Fig. 3 are compared shows that the specimen in Fig. 3 is still somewhat ductile inspite of the surface cracking. At a slover strain rate of 8.4×10^{-7} s⁻¹, the 310 SS (Fig. 4) does not exhibit as much internal intergranular cracking but does reveal larger surface cracks progressing farther into the bulk of the specimen than in the 310 SS specimen tested at the higher strain rate of 3.6 \times 10⁻⁶ s⁻¹ (Fig. 1). Precipitates were seen in the grain boundaries of all the 310 SS specimens regardless of the strain rate at which it was tested. Fig. 5 shows a representative area of grains with grain boundary precipitates in the 310 SS specimens.

Internal intergranular cracking was observed in 310 S stainless steel but only when tested at the slow strain rate of 8.4 \times 10-7 s⁻¹ (Fig. 6). Precipitates were also present in the grain boundaries in all of the 310 S specimens regardless of the strain rate at which they were tested, but the precipitates seemed to be more propounced in the specimen tested at the slow strain rate of $8.4 \times 10^{-7} \text{ s}^{-1}$ (Fig. 7). In the 310 S, with a lower carbon content than 310, there is less carbon present to diffuse to the grain boundaries to form the precipitates; and, therefore, the formation of the precipitates requires longer times. No internal cracking was revealed for any of the 347 St specimens over the range of strain rates tested. No surface cracking was apparent even though several of the specimens showed tool marks on the surface. On the 347 SS specimen (Fig. 8) run at the slow strain rate of 8.4 \times 10⁻⁷ s⁻¹, some of the tool marks opened up in the necked-down area but were shallow and blunt. However, all subsequent specimens tested had tool marks removed by polishing the surface of the reduced area.



No surface cracking and little, if any, internal intergranular cracking could be detected in the Incoloy 800 over the range of strain rates tested. Only the Incoloy 800 specimen tested at 8.4 \times 10⁻⁷ s⁻¹ (Fig. 9) showed a slight indication of internal cracking. There did appear to be some formation of precipitates in the grain boundaries of Incoloy 800 run at strain rates of 7.3 \times 10⁻⁶ s⁻¹ and at 8.4 \times 10⁻⁷ s⁻¹ (Fig. 10).

A determination of the origin of the crack process would help identify the mechanism of cracking, especially with respect to the influence or lack of same of the environment on cracking. However, a thick corrosion product layer on the fracture surface of the 310 stainless steel specimens tested at 540°C (1000°F) in H₂S plus steam or H₂S saturated with water vapor at room temperature prevented a detailed fractographic study of those specimens. However, microscopic examination of the fracture surface of type 310 SS tested in dry helium, argon, and vacuum (house vacuum line, 34 Torr, 4500 Pa) at 540° C (1000° F) and at strain rates $\approx 1 \times 10^{-6} \text{ s}^{-1}$ have revealed evidence of brittle fracture (intergranular cracks and faceted structure) near the original surface of the specimen with ductile fracture (dimples) at the center of the fracture surface and on the shear lip. This indicates that the origin of the crack is at the metal/environment interface and not at the center of the specimen — further evidence that the cracking is. by an environmental mechanism. Fig. 11 shows a representative fracture surface of a 310 SS specimen tested at 540° C (1000°F) and $\approx 1 \times 10^{-6} \text{ s}^{-1}$. Fig. 12 is a photomicrograph of the flat area near edge of fracture surface of Fig. 11. Note the intergranular cracks and faceted structure. Fig. 13 is a photomicrograph of an area near the center of the fracture surface of Fig. 11. Note the dimpled structure indicative of ductile fracture.

To clarify the mechanism of failure, further methods of eliminating the oxygen and water vapor from the test environment are being applied. New flanges were made for the test chamber to facilitate the test of 310 SS in a somewhat better vacuum (2 X 10^{-2} Torr, 2.66 Pa) than that in which the previously tested specimens were tested (house vacuum). Upon completion of the test at $\simeq 1 \times 10^{-5} \text{ s}^{-1}$, the surface of the specimen was oxidized, and the same brittle type fracture occurred with secondary surface cracks. There was apparently enough oxygen and/or water vapor present to cause cracking.

Another test was run on 310 SS. This time a reducing environment (H_2) was used. It was thought that the reducing atmosphere of H_2 would prevent or limit the effect of oxygen. The H_2 was handled in the following manner: the H_2 gas was passed through a liquid N_2 trap, through copper turnings at 565° C (1050° F), through another liquid N_2 trap, through the test chamber at a low positive pressure, through another liquid N_2 trap, and through a H_2 0 bubbler that was vented directed to the exhaust system. This test run was made at 540° C



(1000°F) at a strain rate of $8.4 \times 10^{-7} \text{ s}^{-1}$. Some blue oxide was still present on the specimen after the test, but the amount of oxide was the least that has been seen for any tests in any environment. The fracture was still of the brittle type with some secondary cracking. The reduction in area (23.3%) was higher for this specimen, tested in H₂, than for other 310 SS specimens tested in other environments (17-19%) with the exception of one 310 SS specimen tested at 540°C (1000°F) at a strain rate of $8.4 \times 10^{-7} \text{ s}^{-1}$ in ultra pure He (25%).

Testing of the alloys has been started at a strain rate of 1 \times 10⁻⁷ s⁻¹ in H₂S saturated with water vapor at room temperature at 540°C (1000°F).

Gas mixtures of CO_2 , H_2 , and CH_4 have been prepared and analyzed but have not been shipped since they will be used to calibrate flowmeters that have been ordered. The gases and flow meters are scheduled to be delivered in two weeks.

<u>Plans</u>: Complete tests of types 310, 310 S, 347 stainless steel and Incoloy 800 at the very low strain rate of 1 X 10^{-7} s⁻¹ in H₂S saturated with water vapor at room temperature at 540°C (1000°F), while continuing the search for the cause of failure in the 310 SS.



growth rate as a function of $K_{\rm I}$ or the stress-intensity threshold level below which crack growth rate does not occur can be readily determined. For this configuration of specimen, the stress intensity $(K_{\rm I})$ is then given in terms of the crack length (a), the specimen height (H), the specimen arm displacement due to the wedge (V) and the modulus of the specimen (E) as follows: (ref. 1)

$$K_{I} = \frac{EV}{\sqrt{H}} \left[\frac{3.46 + 2.38 \text{ (H/a)}}{7.97 \left(\frac{a}{H}\right)^2 + 16.48 \left(\frac{a}{H}\right) + 11.32} \right]$$

This equation shows that the stress-intensity $(K_{\underline{I}})$, is relatively insensitive to crack length (a) for a/H values greater than about 3, so that accurate values of $K_{\underline{I}}$ are determined without requiring extremely accurate crack length (a), measurements.

For use at elevated temperature, the above equation for stress-intensity, $K_{_{\!\!T}},$ must take into account the following effects:

- 1) Decrease in elastic modulus, E, with increase in temperature.
- 2) Increase in arm displacement, V, due to thermal expansion.
- 3) Increase in effective crack length, a_{eH}, due to increase in plastic zone size caused by the decrease in the yield strength of the specimen with increase in temperature.
- 4) Decrease in the measurement capacity (maximum stress-intensity that can be measured) for a given size specimen due to decrease in the yield strength of the specimen material.

The equation for stress-intensity given above was modified to take into account these effects. For a wedge-loaded, double cantilever beam specimen loaded at room temperature to a stress-intensity level designated $(K_{\underline{I}})_{0}$, the change in stress-intensity when the temperature is increased to some value T is $(K_{\underline{I}})_{T}$, where the ratio $(K_{\underline{I}})_{T}/(K_{\underline{I}})_{0}$ is:

$$\frac{(K_{\underline{I}})_{\underline{T}}}{(K_{\underline{I}})_{o}} = \frac{E_{\underline{T}}}{E_{o}} \frac{V_{\underline{T}}}{V_{o}} \left(\frac{f(\frac{e_{\underline{T}}}{\underline{I}})}{f(\frac{e_{\underline{T}}}{\underline{H}_{o}})} \right)$$

where:

 $\mathbf{E_{r}}$ - modulus of elasticity of specimen at temperature T.

E - modulus of elasticity of specimen at room temperature.



 $\mathbf{V}_{\mathbf{T}}$ - arm displacement at temperature T.

V - arm displacement at room temperature.

$$f \left(\frac{a_{T}}{H_{T}}\right) = \frac{3.46 + 2.38 \left(\frac{a_{T}}{a_{T}}\right)}{7.97 \left(\frac{a_{T}}{H_{T}}\right)^{2} + 16.48 \left(\frac{a_{T}}{H_{T}}\right) + 11.32}$$

where a_T and H_T are the crack length and specimen height at temperature T $f\left(\frac{a_0}{H_0}\right)$ is the same function for crack length, a_0 , and specimen height, H_0 at room temperature.

It is desirable for temperature to have as small an effect as possible on the stress-intensity. That is, for the ratio $\frac{K_I}{K_O}$ to be approximately 1 over

a wide range of temperature. To achieve this, the effect of temperature on each of the terms in the above equation was investigated to select values than minimize the effect of temperature on the ratio $\frac{K_T}{K_O}$. The effect

of temperature on crack length, a, and specimen height, H, is relatively small and since for a/H ratios greater than about 3, the stress intensity K is relatively unsensitive to a/H, the ratio

 $f(\frac{a_T}{H_T})/f(\frac{a_O}{H_O})$ is approximately 1.0. Therefore the above equation is reduced to:

$$\frac{K_{T}}{K} = \frac{E_{T} V_{T}}{E_{0} V_{0}}$$

where:

$$v_o = h_w - h_s$$

$$V_{T} = [h_{W}(1 + \alpha_{W})(T - T_{O})] - [h_{S}(1 + \alpha_{S})(T - T_{O})]$$

h, - height of wedge at loading point

 $\mathbf{h_s}$ - height of slot in specimen

a - coefficient of thermal expansion of wedge

a - coefficient of thermal expansion of specimen



T - reference temperature (taken as room temperature)

T - test temperature.

Therefore:

$$\frac{K_{T}}{K_{O}} = \frac{E_{T}}{E_{O}} \left[1 + \left(\frac{h_{O}^{\alpha} - h_{O}^{\alpha}}{h_{O} - h_{O}^{\alpha}} \right) (T - T_{O}) \right]$$

For a given test material the choice of wedge size and material is chosen so that as nearly as possible the thermal expansion of the wedge compensates for the decrease in modulus of elasticity of the test specimen with temperature.

Plans: The analysis of the effect of thermal expansion, change in modulus of elasticity with temperature and change in plastic zone size with temperature will be completed. For each of the specific materials of interest for use at high temperature, the elastic stress-intensity factor will be calculated for temperatures up to 2000°F and the maximum stress-intensity for use of linear elastic fracture mechanics will be established.

Reference:

1. B. F. Brown, Stress-Corrosion Cracking in High Strength Steels and in Titanium and Aluminum Alloys, Naval Research Laboratory, 1972 Chap. 2.



2. Ceramic Deformation, Fracture and Erosion (E. R. Fuller, S. M. Wiederhorn, C. R. Robbins and D. E. Roberts, 313.05)

<u>Progress</u>: The main effort of the past quarter has been the design and <u>construction</u> of new test equipment. In addition, the mechanical properties and mineral composition of two laboratory mixtures of castable refractories (high and low alumina calcium-aluminate castables) have been studied after elevated temperature-pressure exposure, and the erosive behavior of a phosphate-bonded refractory has been examined.

A great deal of progress has been made on the construction of the apparatus for mechanical properties testing in simulated coal gasification environments. The outer pressure shell for this apparatus has been constructed. A Radiographic inspection of the original garth welds revealed two flaws which have been repaired. The design of the interior of the apparatus has been completed, detailed mechanical dravings have been prepared, and the components are presently being constructed in the NBS Machine Shop. A base, which will support the pressure vessel, has been designed and is also being constructed. The base will provide explosion protection, and ventilation for the pressure vessel. Other systems and components (such as: temperature controllers, refractory insulation, a pressure-balance controller, and a chain hoist) have been ordered and most have arrived.

The equipment for particle erosion has been enclosed and connected to an exhaust system. The enclosure will satisfy the NBS Safety Office rules on dust/particle hazards and will permit injection of additional gaseous components into the stream of eroding particles. In addition, a ventilation system for exhausting explosive and/or noxious gases from the three pressure vessel systems and the gas tank storage rack has been designed. A spark-proof and corrosion resistant exhaust fan for this system has been ordered, and received, and will be installed shortly.

High-temperature exposure experiments were initiated in a pressure vessel recently purchased by NBS. The unit, has been plagued with a number of minor problems (pressure leaks, a faulty temperature controller, a faulty water pump, and a defective pressure gauge isolation system) which have slowed the collection of data. Nost of these problems have now been overcome and specimens of both a high alumina (~95%) and a low alumina (~56%), calcium-aluminate refractory castable have been exposed to steam at 1000 psig (7.0 MPa) at temperatures running from 310°C (590°F) to 910°C (1670°F). After exposure the following properties have been examined: flexural and compressive strengths at two rates of loading; erosive wear by particle impingement; porosity; mineral phases; and microstructural morphology. Results are still preliminary at this time.



Plans: Construction will continue on the apparatus for mechanical properties testing in simulated coal gasification environments. Completion of the main portions of this apparatus and "check-out" of the heat zone is anticipated in the next quarter. Construction of the ventilation system should begin and be substantially completed in the next quarter. Exposure studies will continue with gaseous compositions (molar percent) of 70% water and 30% carbon dioxide and of 30% water and 70% carbon dioxide at 1000 psig total pressure. Upon completion of the ventilation system, mixtures with carbon monoxide will be considered. Work to characterize the erosion behavior of three basic castable compositions (a 95% alumina, a 56% alumina and a phosphate bonded refractory) as a function of temperature, particle velocity and impingement angle will be completed, and studies on the effect of particle size on erosion rate will be started.

- 3. Chemical Degradation
- a. Reactions and Transformations (F. Mauer and C. R. Robbins, 313.06)

Progress: During this quarter work on the design and construction of apparatus for x-ray examination of refractory castables under simulated gasification conditions was continued. While the pressure vessel was under construction in the NBS Instrument Shops, design of the x-ray goniometer (for mounting and aligning the pressure vessel on the x-ray apparatus) was completed and construction was begun. The pressure vessel and goniometer are expected to be completed by about January 15, 1977.

All of the components for the gas manifold have been purchased. Gases will be introduced through a gauge block that includes a needle valve, pressure gauge and rupture disc. Water will be introduced separately from a 40 ml cylinder pressurized with N_2 gas. A second 40 ml cylinder has been included in the system so that a sample of the atmosphere can be withdrawn for analysis.

Additional samples have been obtained for use in preparing standard xray patterns by the energy dispersive diffraction method. A calculator
program has been written which can be used to convert d-spacings and
intensities from a conventional powder diffraction pattern to channel
number and counts (peak and background) for the energy dispersive diffraction pattern. This program is being used in the interpretation of the
patterns being prepared for use as working standards.

Plans: Construction of major components is expected to be completed during January so that the system can be assembled during February and used for calibration runs. In situ x-ray diffraction measurements (subtask 3a-3) are expected to begin by April 1, 1977, as proposed in our original work statement.



b. Slag Characterization (W.S. Brower, J.L. Waring, 313.03 and D.H. Blackburn, 313.02)

<u>Progress</u>: The viscosities of synthetic slags (one modeled after Montana Rosebud Coal Ash analyses and the other modeled after Pittsburgh Seam Coal Ash) have been measured at ambient pressure over the temperature range of 1300°C to 1600°C (Figure 1a and 1b). The compositions are given in Table 1.

Table 1. Slag Compositions

Ros	ebud	Pittsburgh Seam			
SiO ₂	42.10 wt%	SiO ₂	49.0 wt%		
A1 ₂ 0 ₃	19.50	A1 ₂ 0 ₃	26.0		
Fe ₂ O ₃	7.11	Fe ₂ 0 ₃	19.0		
Ca0	24.48	Ca0	3.5		
Na ₂ 0	0.21	Na ₂ 0	0.6		
K20	0.10	K ₂ O	1.2		
MgO	5.50	MgO	0.7		
TiO ₂	0.90				

The gear motor for crucible rotation has been received and the torsion wire suspensions have been calibrated with two fluids of known viscosity using two different "drag cup geometries" (Figure 2).

Preliminary tests have been run in an actoclave operating at 30 psig steam pressure using a platinum strip heater with a radiating area of 15 square inches to evaluate the effect of steam pressure on the heater temperature at a constant power level. A 20% reduction in temperature was observed from ambient pressure to 30 psig (Figure 3) at 800°C.


Plans: While the pressure vessel construction is being completed a series of synthetic slags with systematically varying composition will be formulated and the viscosities measured is a function of temperature and compared to viscosity data obtained from predictive equations. In the next quarter the vessel construction should be complete.



1800 1600 Figure la. Viscosity of synthetic slag vs temperature. 1400 Rosebud Type Coal Ash 1200 VISCOSITY (log₁₀ Poises)


TEMPERATURE °C






56 VISCOSITY (log₁₀ poises)





TININ BEAUTION SEE WINNIE





TEMPERATURE °C



c. Vaporization and Chemical Transport (J. Hastie and D. Bonnell, 313.01)

<u>Progress</u>: Quantitative vapor transport data have been obtained for molten Na_2SO_4 in an argon environment using our prototype platinum tube reactor. A wide range of pressures (0.15 to 0.6 atm) and temperatures (1390 K to 1650 K) were used to test reactor performance and attainment of thermodynamic equilibrium. The major vapor transport reaction in this system was determined as

$$Na_2SO_4$$
 (l) = $2Na + SO_2 + O_2$

and by monitoring mass spectrometrically the partial pressures of Na, SO_2 , and O_2 values for the apparent reaction equilibrium constant could be determined, i.e.,

$$K_p = (pNa)^2 (pSO_2) (pO_2)$$

Also, from the so-called second law dependence of K_p on temperature, a value for the reaction enthalpy was determined as ΔH_r (1520 K) = 283±13 kcal mol⁻¹. This result is in agreement with the literature value of 287 kcal mol⁻¹ (JANAF Thermochemical Tables). Similarly the absolute values of K_p agree within experimental error with the literature values based on thermodynamic equilibria. Such agreement provides good evidence that the liquid Na₂SO₄ vaporization process in an equilibrium one and that our reactor design and sampling conditions are not distrubing the reaction. These data also establish the lower sensitivity limit for the technique as 1 ppm per mole of carrier gas.

Plans: Though the present reactor design has performed satisfactorily thus far we intend to decrease the cone angle of the skimmer for aerodynamic reasons. This should allow for improved sensitivity at higher gas pressures. Following construction of this new skimmer we will test the system with NaCl by monitoring the well known vapor equilibrium:

$$2NaC1 = (NaC1)_2$$

Once the modified reactor has been shown to perform satisfactorily for the relatively simple test systems, the inert argon atmosphere will be replaced by reactive gases, $\rm H_2O$, $\rm H_2$, $\rm SO_2$, etc., common to coal gasification reactors. Measurements of vapor composition as a function of temperature, pressure, and composition will then be made.



4. Failure Avoidance Programs (J. H. Smith, 312.01)

Progress: Approximately 50 additional reports of operating discrepancies and component failures in coal conversion pilot plants were received in the Failure Prevention Information Center during the current quarter. Additional information on the performance of materials in coal conversion process equipment was received from technical papers presented at the 8th Synthetic Pipeline Gas Symposium and on the properties of high temperature alloys from papers presented at the Electrochemical Society meeting.

All information on operating discrepancies, component failures, and materials performance have been classified and evaluated for technical completeness and accuracy. Detailed technical abstracts of this information have been entered into the computerized data base management system for ease of future retrieval and data dissemination. An update of the frequency of failure modes which analyses the information in this system is shown in Table 1.

Information was disseminated by supplying abstracts of information included in the data base on a weekly basis to Battelle - Columbus for use in preparation of the Materials and Components Newsletter and to other users as requested. In addition, requests for specific, detailed information were supplied to approximately 15 organizations in response to direct inquiries to the Failure Prevention Information Center.

Beginning with the December 1, 1976 edition of the Materials and Components Newsletter, descriptions of operating discrepancies and component failures are referred to by NBS information item number for convenience in referring to specific failure problems.

The format was developed for two separate types of reports to be used for efficiently disseminating information from the Failure Prevention Information Center. A draft of the first abstract report on information about the use of 316 stainless steel has been completed.

A draft of a detailed summary report on erosion in coal conversion process equipment has been completed.

Plans: The information collecting phase of this task will continue as more information is received on a continuing basis from the pilot plants. Visits to operating pilot plants and failure analysis laboratories are planned to significantly augment the information collection activities and to get additional information on operating discrepancies and component failures.

The information evaluation phase of this task will include development of additional programs for use with the data base system. In addition, the information classification scheme will be revised and improved.



A series of detailed abstract reports are being prepared in several topical areas including materials of construction and failure mode. A second detailed summary report on the topic of sulfidation is being prepared and will be completed during the next quarter.



EVECUERICY OF FAILURE MODE

TABLE 1

カ ー	S		7.	7		ST	BUALITY CONTRIL
Ţ	E T		Z	7 T	. <u>/</u>		Of her HELDING
	; :	! 			ř	75	. NOITADIREAT
TT	.7		9	ΰ		30	. 70 - 008
		:					2де 22 г. В Стина
7	i	7			L		ТАКЯЗНТ
7	T	· 0T	ε	9	77		реиеваг
						33	ДЕЗІСИ ЭЕГЕСТ
97		9	ZZ	32	T05		ОЕИЕЯАГ
τ	·		7	9	6		, GARB,
				3	ε		Dusting
	•		7	7	7	!	DNITTI
						811	Соввојатои
21	; 9	8	9	9		۲۶	Екоѕгои
	.		۷.	ŢŢ		77	SULFIDATION
7	13	ε	6	9		35	Пиретекмі иер
Отнека	. Зиднтиу2	SRC	saayl!	200	ITEMS		ІИСІДЕИТ
					No. oF		FO SEUAD



(8	12-	7 . V	3H)	F. P.	NED-1

USCOMM-DC 29042-F	and the same of th	74,m 4,734,7 ±4	en e de la companya d					
100	CLASSIFIED	NU	(SIT	M) Service (M	oindəəT lenois 18182 sinig	Order From Na Springfield, Vi		
22. Price	HIS BVCE) ECNEILK CLASS	50 ° SE	esii	10 animing Jasamarsvoð 🤞	p. of Do c. , U.S	Order From Sul Washington, O		
	NCF V22IEIED	10 J.	BS will no	o Not Release to NTIS NJ FE will submit af	istribution. D IS; ERDA—I	XX For Official D.		
SJ. NO. OF PAGES	HIS REPORT)	T) SE		bəsimilaU [18. AVAILABILITY		
	_			6226525		7		
fenimeda extra	sera simeras.	noisors:	n, ceramic	es; alphabetical order; cap Ceramic corrosion fication material	semicolons)	kg pajejedas !aweu		
	The state of the s	. 0						
A SANT								

prince and the second								
	·							
	The state of the s					*		
odram	Id annergiice bi	וב דמדדתד	C	astmaig tolig mo	COUNCERS	Lecs ACAH TOI		
cost	se related to	rolited eq	mical deg:	erosion, and che This report also	everems,	deformation,		
anic	derosion, cer	stom , noi	corred is	overs mork on mot	s report c	seapozd stul		
านความ เส ียร	D CORNIGHT AMARMACO		************************************	montion it here.)				
, we or i ji rap i o	o c sopilioni di anni	31	,	ischel summer of most	889[10 P10M-0	16. ABSTRACT (A 20		
	-				k noles	12. SUPPLEMENTAR		
ng Agency Code .t. UC-90C	Dist. Ca			D. C. 20545	'uoıbuşqs	Mar		
Dec. 30, 1976	Ocf. 1 -	HOTONTO	***************	etts Avenue				
Sustant of Period	Covered	12. Sponsoring Organization Name and Complete Address (Stroot, City, State, ZIP) Energy Research and Development Administration						
Peper & Period		\@12		12) coult cicles to	o creid seiter	inearO animonada .51		
МАЗНІМЕТОИ, D.C. 20234 МАЗНІМЕТОИ, D.C. 20234 В (49-1) 3800 В (49-1) 3800 В (49-1) 3800						ī		
Task/Work Unit No.	10. Project/	S. PERFORMING ORGANIZATION NAME AND ADDRESS 10. Pto						
1g Organ. Report No.	8. Performin	7. AUTHOR(S) Samuel J. Schneider, Jr.						
9boD noitzafins 310 g:	6. Performin	9/6T 105	- necewper	· T zegozon 'zzode	rodress ke	Личенту Р		
9461 4	ре с ешре	"MATERIALS RESEARCH FOR CLEAN UTILIZATION OF COAL"						
on Date	5. Publicati		· r · · · · · · · · · · · · · · · · · ·		ITLE	4. TITLE AND SUBT		
		.oN	30,00	FE-1380	ATAG	SHEETOGRAPHIC SHEET		
.oV. Accession No.	ssion 3. Recipien	2. Gov't Acce	RT NO.	PUBLICATION OR REPC		U.S. DEPT. OF CO		

